

Changes to the CANAL+ services

Canal+ is to change the service line up 27th August 2010.

Satellite: Thor 5
Transponder: C05
Downlink frequency: 11278 MHz
Downlink polarisation: Vertical
Symbol rate: 24.5 Msym/sec
Forward Error Correction: 7/8

CANAL+ FOTBALL

CANAL+ FOTBALL replaces CANAL+ SPORT 1 (N)

Service ID: 306
PMT PID: 260
Video PID: 516 (including PCR)
Audio PID: 690
Teletext PID: 577
ECM PID: 36

CANAL+ FOTBOLL

CANAL+ FOTBOLL, New Service

Service ID: 320
PMT PID: 269
Video PID: 520 (including PCR)
Audio PID: 696
ECM PID: 41

Satellite: Thor 5
Transponder: C04
Downlink frequency: 11260 MHz
Downlink polarisation: Horizontal
Symbol rate: 24.5 Msym/sec
Forward Error Correction: 7/8

CANAL+ EXTRA

CANAL+ EXTRA 4, New Service in timeshare with CANAL+ SPORT EXTRA

Service ID: 3320
PMT PID: 266
Video PID: 522 (including PCR)
Audio PID: 684
ECM PID: 110

CANAL+ HOCKEY

CANAL+ HOCKEY replaces TV-biljett 4

Service ID: 3404
PMT PID: 264
Video PID: 520 (including PCR)
Audio PID: 676
ECM PID: 108

CANAL+ **SPORT 3**

CANAL+ SPORT 3 replaces TV-biljett 5

Service ID: 3405
PMT PID: 265
Video PID: 521 (including PCR)
Audio PID: 680
ECM PID: 109

Satellite: Thor 5

Transponder: C09

Downlink frequency: 11341 MHz

Downlink polarisation: Vertical

Symbol rate: 24.5 Msym/sec

Forward Error Correction: 7/8

CANAL+ **EXTRA**

CANAL+ EXTRA 1 replaces TV-biljett 1

Service ID: 2104
PMT PID: 262
Video PID: 516 (including PCR)
Audio PID: 660
ECM PID: 68

CANAL+ **EXTRA**

CANAL+ EXTRA 2 replaces TV-biljett 2

Service ID: 2105
PMT PID: 263
Video PID: 517 (including PCR)
Audio PID: 664
ECM PID: 69

CANAL+ **EXTRA**

CANAL+ EXTRA 3 replaces TV-biljett 3

Service ID: 2109
PMT PID: 256
Video PID: 512 (including PCR)
Audio PID: 640
ECM PID: 64

Svein Bråten

Senior System Architect - DVB

Telenor Satellite Broadcasting